



PHOTO 1 – Before external wall insulation



PHOTO 2 – After external wall insulation



PHOTO 3 – Timber cladding




PHOTO 4 - Brick slips



PHOTO 5 – timber sliding sash window



PHOTO 6 – Internal secondary glazing to sash window



PHOTO 7 – Solar panels on front roof slope



PHOTO 8 – External draught lobby

Credits – Photos 1, 2 & 7 were supplied by Victorian Terrace Energy Reduction Initiative (VICTERI) [www.victeri.co.uk](http://www.victeri.co.uk)